



29

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of


U.S. Patent No. : 7,105,954 B2  
Issued : September 12, 2006  
Serial No. : 10/614,854  
Title : SENSOR INTERFACE CABLE  
Docket No. : HYD 012 PA

**Certificate**  
APR 19 2007  
**of Correction**

Commissioner for Patents  
Certificate of Correction Branch  
PO Box 1450  
Alexandria VA 22313-1450

CERTIFICATE OF MAILING

I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to: Commissioner for Patents, Certificate of Correction Branch, PO Box 1450, Alexandria, VA 22313 on April 12, 2007.

  
\_\_\_\_\_  
Attorney

Reg. No. 33,348

Sir:

REQUEST FOR CERTIFICATE OF CORRECTION FOR PTO MISTAKES  
UNDER 35 U.S.C. 254 AND 37 C.F.R. 1.322

In the matter of U. S. Patent No. 7,105,954 B2, it is respectfully requested that a Certificate of Correction be issued to cover the following errors which occurred in the printing of the patent.

Col. 2, line 23, "first sensor leads the second cable" should read --first sensor leads; the second cable--;

Col. 4, line 13, "26, 28. When the output" should read --26, 28. (New paragraph)  
When the output--;

Col. 4, line 36, "circuit board 90 is approximately 5:1 times" should read --circuit board 90 is approximately 5.1 times--;

Col. 4, line 67, "comprises **18** AWG cable, " should read --comprises 18 AWG cable (no bold)--;

Col. 5, line 2, "comprises **22** AWG cable, " should read --comprises 22 AWG cable (no bold)--.


APR 19 2007

REMARKS

It is respectfully requested that a Certificate of Correction be issued for the above-identified patent. All of the above errors occurred during the printing of the patent and, therefore, no fee is due. Two (2) copies of the required Certificate of Correction Form PTO/SB/44 are enclosed.

Respectfully submitted,

STEVENS & SHOWALTER, L.L.P.



Michael D. Folkerts  
Reg. No. 33,348

7019 Corporate Way  
Dayton OH 45459-4238  
Telephone: 937/438-6848  
Facsimile: 937/438-2124  
Email: mfolkerts@sspatlaw.com

APR 19 2007

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 7,105,954 B2  
DATED : September 12, 2006  
INVENTOR(S) : Rand Kalani Ray

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Col. 2, line 23, "first sensor leads the second cable" should read --first sensor leads; the second cable--;

Col. 4, line 13, "26, 28. When the output" should read --26, 28. (New paragraph)  
When the output--;

Col. 4, line 36, "circuit board 90 is approximately 5:1 times" should read --circuit board 90 is approximately 5.1 times--;

Col. 4, line 67, "comprises 18 AWG cable, " should read --comprises 18 AWG cable (no bold)--;

Col. 5, line 2, "comprises 22 AWG cable, " should read --comprises 22 AWG cable (no bold)--.

APR 19 2007

**MAILING ADDRESS OF SENDER:**

Michael D. Folkerts  
Stevens & Showalter LLP  
7019 Corporate Way  
Dayton OH 45459-4238

PATENT NO. 7,105,954 B2 APR 19 2007

No. of additional copies



This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: **Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.**

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

APR 19 2007